

## RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 12236

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080079-7

RECEIVED FROM

DATE REC'D. 5-22-57

P.O. NO.

VENDOR PACKING SLIP NO.

Plant #9

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO. S.O. NO.
	122	000000	143	0	10				
2	731655 Motor Intervalometer					QUANTITY		REMARKS	
						ACCEPTED	REJECTED		
						2		In Store	
	IP# 7722								

RECEIVED  
BYINSPECTED  
BY

DATE

REJECTS RETURNED  
ON SHIP. MEMO NO.

## RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 12241

2761 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 5-22-57

P.O. NO.

VENDOR PACKING SLIP NO.

Plant #9

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO. S.O. NO.
	122	000000	069	0	12	1			
27	730125-9 Relay IPDY-28V MED-SD-26.5 with sockets					QUANTITY		REMARKS	
						ACCEPTED	REJECTED		
						27		In Store	
	IP# 7724 & 7723								

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080079-7

RECEIVED  
BYINSPECTED  
BY

DATE

REJECTS RETURNED  
ON SHIP. MEMO NO.